



Visible and infrared photo of MMTS placement on tower above a parking lot at Grants Pass, OR, USHCN station. In the bottom photo, air conditioner units that produce warm exhaust that rises can be seen. This is a Class 5 station, wholly unsuitable for climate measurements, and likely the worst station in the entire 2022 survey. Source: Anthony Watts.